



Lead Service Line Inventory Template

*Please enter information in the empty box next to each section	Water System Name		Loami Water			System ID Number:		ILG580275		Current Inventory Date:		4/1/2024									
*Please enter totals in the empty box next to each category	Total Service lines:		379		Total Lead:	0		Total Non-Lead:	287		Total Galvanized Requiring replacement:		0		Total Unknown:	92		Website link to Material Inventory:			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property				
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or " LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.				
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)											
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Copper - Lead Solder (CLS)											
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Galvanized (G)											
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Lead (L)											
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)		Cast/Ductile Iron or Transite (O)											
		Plastic - PVC, HDPE, PEX (P)					Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Plastic - PVC, HDPE, PEX (P)											
		Unknown (U)					Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Plastic - PVC, HDPE, PEX (P)											
		Unknown Not Lead (UNL)					Unknown (U)	Unknown (U)		Unknown (U)											
							Unknown Not Lead (UNL)	Unknown Not Lead (UNL)		Unknown Not Lead (UNL)											
285 WITT ST		N				Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N								
297 WITT ST		N			1990's	Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N								
506 RESERVOIR RD		N			1990's	Survry response		C	C	NL	N	N/R	N								
502 RESERVOIR RD		N			2006	Survry response		C	C	NL	N	N/R	N								
212 WITT ST		N				Maintenance records		C	UNL	NL	N	N/R	N								
210 WITT ST		N			1998	Survey response		C	C	NL	N	N/R	N								
205 WITT ST	LP3S009	N				Maintenance records		C	UNL	NL	N	N/R	N								
208 WITT ST		N				Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N								
206 WITT ST		N			2002	Survry response		C	C	NL	N	N/R	N								
203 WITT ST		N			1970's	Survry response		C	C	NL	N	N/R	N								
201 WITT ST		N				Maintenance records		C	UNL	NL	N	N/R	N								
200 WITT ST		N				Survey response		C	C	NL	N	N/R	N								
219 MILL ST	LP3S022	N				Maintenance records		C	UNL	NL	N	N/R	N								
217 MILL ST		N				Maintenance records		C	UNL	NL	N	N/R	N								
215 MILL ST		N				Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N								
213 MILL ST		N				Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N								
205 MILL ST		N				Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N								
202 MILL ST		N				Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N								
208 MILL ST		N				Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N								
214 MILL ST		N				Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N								
216 MILL ST		N			1997	Survry response		C	C	NL	N	N/R	N								
218 MILL ST		N			2001	Survry response		C	C	NL	N	N/R	N								
115 WITT ST		N				Maintenance records		P	C	NL	N	N/R	N								

111 WITT ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
110 WITT ST	LP1A015	N			Unknown	Survey reponse		P	C	NL	N	N/R	N				
106 WITT ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
109 WITT ST		N				Survey response		C	C	NL	N	N/R	N				
104 WITT ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
100 WITT ST		N				Visual inspection		C	C	NL	N	N/R	N				
9091 JOHNS CREEK RD		N				Maintenance records		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
9123 JOHNS CREEK RD		N				Maintenance records		C	C	NL	N	N/R	N				
9125 JOHNS CREEK RD		N				Maintenance records		C	C	NL	N	N/R	N				
9131 JOHNS CREEK RD		N				Maintenance records		C	C	NL	N	N/R	N				
9189 JOHNS CREEK RD		N			Unknown	Survey response		C	C	NL	N	N/R	N				
9197 JOHNS CREEK RD		N				Maintenance records		C	UNL	NL	N	N/R	N				
9188 JOHNS CREEK RD		N			1969	Survey response		C	C	NL	N	N/R	N				
9130 JOHNS CREEK RD		N				Maintenance records		C	UNL	NL	N	N/R	N				
9110 JOHNS CREEK RD		N				Maintenance records		C	UNL	NL	N	N/R	N				
9100 JOHNS CREEK RD		N				Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
9096 JOHNS CREEK RD		N			1970's	Survey response		C	C	NL	N	N/R	N				
9050 JOHNS CREEK RD		N				Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
324 S MAIN ST		N				Maintenance records		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
307 S MAIN ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
302 S MAIN ST		N				Maintenance records		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
104 S MAIN ST		N				Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
106 S MAIN ST		N				Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
110 S MAIN ST		N			Unknown	Survey response		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
112 S MAIN ST		N				Maintenance records		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
114 S MAIN ST		N				Maintenance records		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
116 S MAIN ST		N			1990'S	Survey response		C	C	NL	N	N/R	N				
118 S MAIN ST		N				Survey response		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
122 S MAIN ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
124 S MAIN ST		N				Survey response		C	C	NL	N	N/R	N				
202 S MAIN ST		N			Unknown	Survey response		C	G	NL	N	N/R	N				
204 S MAIN ST		N			Unknown	Survey response		C	G	NL	N	N/R	N				
205 S MAIN ST	LP1A024	N				Maintenance records		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
202 SMITH ST	LA3S025	N				Maintenance records		C	UNL	NL	N	N/R	N				
129 S MAIN ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
125 S MAIN ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
123 S MAIN ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
121 S MAIN ST	LA3S001	N				Maintenance records		C	UNL	NL	N	N/R	N				
117 S MAIN ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
113 S MAIN ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
100 CHURCH ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
102 CHURCH ST		N			1980's	Survey response		C	C	NL	N	N/R	N				
106 CHURCH ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
105 CHURCH ST		N			1995	Survey response		C	C	NL	N	N/R	N				
602 N MAIN ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				

100 N MAIN ST		N				Maintenance records		C	C	NL	N	N/R	N				
101 N MAIN ST	LP3S018	N				Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
102 W CENTER ST	LP3S011	N				Maintenance records		C	C	NL	N	N/R	N				
104 W CENTER ST		N			1990's	Survey response		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
106 W CENTER ST	LP3S010	N				Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
110 W CENTER ST		N				Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
112 W CENTER ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
114 W CENTER ST		N				Maintenance records		C	C	NL	N	N/R	N				
116 W CENTER ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
118 W CENTER ST		N				Maintenance records		C	C	NL	N	N/R	N				
120 W CENTER ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
122 W CENTER ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
126 W CENTER ST		N			1974	Survey response		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
201 NICHOLS LN		N			1999	Survey response		C	C	NL	N	N/R	N				
203 NICHOLS LN		N				Visual inspection		C	C	NL	N	N/R	N				
205 NICHOLS LN		N			1990's	Survey response		C	C	NL	N	N/R	N				
207 NICHOLS LN		N				Maintenance records		C	C	NL	N	N/R	N				
209 NICHOLS LN		N				Maintenance records		C	C	NL	N	N/R	N				
210 NICHOLS LN		N				Maintenance records		C	C	NL	N	N/R	N				
208 NICHOLS LN		N				Maintenance records		C	C	NL	N	N/R	N				
206 NICHOLS LN		N			Unknown	Survey response		C	C	NL	N	N/R	N				
204 NICHOLS LN		N				Maintenance records		C	C	NL	N	N/R	N				
202 NICHOLS LN		N				Maintenance records		C	C	NL	N	N/R	N				
200 NICHOLS LN		N				Maintenance records		C	C	NL	N	N/R	N				
100 SAWMILL LN		N			2004	Survey response		C	C	NL	N	N/R	N				
102 SAWMILL LN		N			1990	Survey response		C	C	NL	N	N/R	N				
104 SAWMILL LANE		N			2009	Survey response		C	C	NL	N	N/R	N				
123 W CENTER		N			1995	Survey response		C	C	NL	N	N/R	N				
121 W CENTER S		N			1960's	Survey response		C	C	NL	N	N/R	N				
119 W CENTER ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
117 W CENTER S		N			2004	Survey response		C	C	NL	N	N/R	N				
115 W CENTER S		N				Maintenance records		C	C	NL	N	N/R	N				
113 W CENTER		N				Maintenance records		C	C	NL	N	N/R	N				
1108 VINEGAR HILL		N				Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
1102 VINEGAR HILL LN		N				Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
111 W CENTER ST		N			Unknown	Survey response		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
103 W CENTER ST		N				Maintenance records		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
1 GARNER LN		N				Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
104 N MAIN ST		N			1996	Survey response		C	C	NL	N	N/R	N				
406 N MAIN ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
104 EAST COLBURN		N				Historical records		C	UNL	NL	N	N/R	N				
106 EAST COLBURN		N				Historical records		C	UNL	NL	N	N/R	N				
108 EAST COLBURN		N				Historical records		C	UNL	NL	N	N/R	N				
110 EAST COLBURN		N				Historical records		C	UNL	NL	N	N/R	N				
112 EAST COLBURN		N				Historical records		C	UNL	NL	N	N/R	N				

107 E Colburn		N				Historical records		C	UNL	NL	N	N/R	N				
103 EAST COLBURN	LP3S019	N				Maintenance records		C	UNL	NL	N	N/R	N				
502 N MAIN ST		N			Unknown	Survey response		C	G	NL	N	N/R	N				
504 N MAIN ST		N				Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
608 N MAIN ST		N			1978	Survey response		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
610 N MAIN ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
612 N MAIN ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
306 MEACHAM STREE		N				Maintenance records		C	UNL	NL	N	N/R	N				
308 MEACHUM STREE		N				Maintenance records		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
305 MEACHAM STREE		N				Maintenance records		C	UNL	NL	N	N/R	N				
721 N MAIN ST		N				Survey response		C	C	NL	N	N/R	N				
719 N MAIN ST		N				Maintenance records		C	C	NL	N	N/R	N				
717 N MAIN ST	LA3S021	N			1990	Survey response		C	C	NL	N	N/R	N				
715 N MAIN ST	LP3S020	N				Maintenance records		C	UNL	NL	N	N/R	N				
713 N MAIN ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
711 N MAIN ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
709 N MAIN ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
707 N MAIN ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
705 N MAIN ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
703 N MAIN ST		N				Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
701 N MAIN ST		N				Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
601 N MAIN ST		N			1975	Survey response		C	C	NL	N	N/R	N				
539 N MAIN ST		N			2023	Survey response		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
503 N MAIN ST		N				Maintenance records		C	C	NL	N	N/R	N				
501 N MAIN ST		N				Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
109 W COLBURN ST		N			2005	Survey response		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
101 W COLBURN ST		N				Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
407 N MAIN ST		N			1980's	Survey response		C	C	NL	N	N/R	N				
405 N MAIN ST		N				Maintenance records		C	C	NL	N	N/R	N				
403 N MAIN ST	LP3S006	N				Maintenance records		C	C	NL	N	N/R	N				
303 N MAIN ST		N				Maintenance records		C	C	NL	N	N/R	N				
203 N MAIN ST		N				Maintenance records		C	C	NL	N	N/R	N				
201 N MAIN ST		N				Maintenance records		C	C	NL	N	N/R	N				
105 N MAIN ST		N			1962	Survey response		C	C	NL	N	N/R	N				
103 N MAIN ST		N				Maintenance records		C	C	NL	N	N/R	N				
309 N EAST ST		N				Maintenance records		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
307 N EAST ST		N			2020	Survey response		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
305 N EAST ST		N				Maintenance records		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
301 N EAST ST		N			2020	Survey response		C	C	NL	N	N/R	N				
302 N EAST STREET		N				Maintenance records		C	UNL	NL	N	N/R	N				
206 N EAST ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
302 CARSON ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
303 CARSON ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
304 CARSON ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
306 CARSON ST		N			Unknown	Survey response		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				

308 CARSON ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
305 CROSS ST		N				Maintenance records		C	C	NL	N	N/R	N				
308 CROSS ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
402 CARSON ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
404 CARSON ST		N				Maintenance records		C	C	NL	N	N/R	N				
406 CARSON ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
408 CARSON ST	LP3S012	N			2018	Maintenance records		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
202 EVANS ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
310 ELM ST		N				Maintenance records		C	C	NL	N	N/R	N				
309 ELM ST		N			2025	Maintenance records		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
308 ELM STREET		N			Unknown	Survey response		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
307 ELM STREET		N				Visual inspection		C	C	NL	N	N/R	N				
305 ELM ST		N				Maintenance records		C	C	NL	N	N/R	N				
304 ELM ST		N				Maintenance records		C	C	NL	N	N/R	N				
302 ELM ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
301 ELM ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
215 ELM ST		N			Unknown	Survey response		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
309 EAST CENTER S		N			Unknown	Survey response		P	C	NL	N	N/R	N				
207 ELM ST		N				Maintenance records		C	C	NL	N	N/R	N				
205 ELM ST	LP3S008	N				Maintenance records		C	C	NL	N	N/R	N				
204 ELM ST		N				Maintenance records		C	C	NL	N	N/R	N				
204 N EAST ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
203 N EAST ST	LP3S023	N				Maintenance records		C	C	NL	N	N/R	N				
207 N EAST ST		N			1957	Visual inspection		C	C	NL	N	N/R	N				
203 NARROW ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
201 NARROW ST		N				Maintenance records		C	C	NL	N	N/R	N				
304 SUNSET LN		N				Visual inspection		C	C	NL	N	N/R	N				
306 SUNSET LN		N				Maintenance records		C	UNL	NL	N	N/R	N				
308 SUNSET LN		N			2019	Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
307 SUNSET LN		N			Unknown	Survey response		C	C	NL	N	N/R	N				
305 SUNSET LN		N			Unknown	Survey response		C	G	NL	N	N/R	N				
109 NARROW ST		N				Maintenance records		C	C	NL	N	N/R	N				
107 NARROW ST	LP1A017	N			1980's	Survey response		C	C	NL	N	N/R	N				
103 NARROW ST		N			2022	Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
101 NARROW ST		N				Maintenance records		C	C	NL	N	N/R	N				
106 N MAIN ST		N			1996	Survey response		C	C	NL	N	N/R	N				
106 MAPLE ST	LP1A005	N				Historical records		C	UNL	NL	N	N/R	N				
108 MAPLE ST		N				Historical records		C	UNL	NL	N	N/R	N				
110 EAST MAPLE ST		N				Historical records		C	UNL	NL	N	N/R	N				
112 EAST MAPLE ST		N				Historical records		C	UNL	NL	N	N/R	N				
114 EAST MAPLE ST		N				Maintenance records		C	C	NL	N	N/R	N				
116 EAST MAPLE ST	LP1A007	N			1982	Survey response		C	C	NL	N	N/R	N				
118 EAST MAPLE ST		N				Historical records		C	UNL	NL	N	N/R	N				
105 N EAST ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
301 EAST CENTER S		N				Maintenance records		C	UNL	NL	N	N/R	N				

104 N EAST ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
115 EAST MAPLE ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
111 EAST MAPLE ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
109 MAPLE ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
107 EAST MAPLE ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
105 EAST MAPLE ST		N			Unknown	Survey response		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
103 MAPLE ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
302 N MAIN ST		N			1990's	Survey response		C	C	NL	N	N/R	N				
102 NARROW ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
104 NARROW ST		N				Survey response		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
108 NARROW ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
110 NARROW ST	LP3S004	N			1966	Survey response		C	C	NL	N	N/R	N				
204 NARROW ST		N			2018	Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
101 S EAST ST		N				Historical records		C	UNL	NL	N	N/R	N				
302 EAST CENTER ST		N				Visual inspection		C	C	NL	N	N/R	N				
304 EAST CENTER ST		N				Historical records		C	UNL	NL	N	N/R	N				
306 EAST CENTER ST		N				Maintenance records		C	C	NL	N	N/R	N				
308 EAST CENTER S		N				Maintenance records		C	UNL	NL	N	N/R	N				
310 EAST CENTER S		N			1967	Survey response		C	C	NL	N	N/R	N				
402-4 EAST CENTER ST		N				Historical records		C	UNL	NL	N	N/R	N				
402-3 EAST CENTER ST		N				Historical records		C	UNL	NL	N	N/R	N				
402-2 EAST CENTER	LP1A013	N				Historical records		C	UNL	NL	N	N/R	N				
402-1 EAST CENTER ST		N				Historical records		C	UNL	NL	N	N/R	N				
109 RUMBLE LN		N			2018	Survey response		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
105 RUMBLE LN		N				Maintenance records		C	UNL	NL	N	N/R	N				
106 RUMBLE LN		N				Maintenance records		C	UNL	NL	N	N/R	N				
408 EAST CENTER ST		N			1995	Survey response		C	C	NL	N	N/R	N				
409 EAST CENTER ST		N			2018	Survey response		C	C	NL	N	N/R	N				
407 EAST CENTER ST		N				Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
405 EAST CENTER ST		N			2017	Survey response		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
403 EAST CENTER ST		N				Maintenance records		C	C	NL	N	N/R	N				
401 EAST CENTER ST	LA3S014	N			1968	Survey response		C	C	NL	N	N/R	N				
305 EAST CENTER ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
303 EAST CENTER ST		N				Maintenance records		C	C	NL	N	N/R	N				
215 CHURCH ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
213 CHURCH ST		N				Maintenance records		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
211 CHURCH ST		N				Maintenance records		C	C	NL	N	N/R	N				
203 CHURCH ST		N				Maintenance records		C	C	NL	N	N/R	N				
201 CHURCH ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
109 CHURCH ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
108 CHURCH ST		N				Maintenance records		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
112 COLEY ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
114 COLEY ST		N			Unknown	Survey response		C	G	NL	N	N/R	N				
116 COLEY ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
118 COLEY ST		N				Maintenance records		C	C	NL	N	N/R	N				

204 SMITH ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
205 SMITH ST		N				Maintenance records		C	NO LINE/VACANT	NL	N	N/R	N				
306 SMITH ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
312 SMITH ST		N				Maintenance records		P	UNL	NL	N	N/R	N				
310 SMITH ST		N				Maintenance records		P	UNL	NL	N	N/R	N				
316 SMITH ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
304 S EAST ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
306 S EAST ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
301 S COLEY ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
308 S EAST ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
310 S EAST ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
312 S EAST ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
318 S EAST ST		N			1989	Survey response		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
301 S EAST ST		N			Unknown	Survey response		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
217 S EAST ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
215 S EAST ST		N			Unknown	Survey response		C	C	NL	N	N/R	N				
209 S EAST ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
207 S EAST ST	LP3S016	N				Maintenance records		C	UNL	NL	N	N/R	N				
205 S EAST ST	LP3S002	N				Maintenance records		C	UNL	NL	N	N/R	N				
203 S EAST ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
201 S EAST ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
106 S EAST ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
208 S EAST ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
210 S EAST ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
212 S EAST ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
307 SMITH ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
305 SMITH ST		N				Maintenance records		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
119 COLEY ST		N				Maintenance records		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
115 COLEY ST		N			2019	Survey response		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
113 COLEY ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
111 COLEY ST	LA3S003	N			Unknown	Survey response		C	C	NL	N	N/R	N				
109 COLEY ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
107 COLEY ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
105 COLEY ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
206 CHURCH ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
208 CHURCH ST		N				Maintenance records		C	UNL	NL	N	N/R	N				
212 CHURCH ST		N				Maintenance records		C	C	NL	N	N/R	N				
9200 EAST LOAMI RD		N				Maintenance records		C	UNL	NL	N	N/R	N				
9180 EAST LOAMI RD		N				Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
9130 EAST LOAMI RD		N			1994	Survey response		C	C	NL	N	N/R	N				
9126 OAK GROVE RO		N				Maintenance records		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
8050 EAST LOAMI R		N				Maintenance records		C	UNL	NL	N	N/R	N				
9063 CURRAN RD		N				Maintenance records		C	UNL	NL	N	N/R	N				
8300 REYHAN RD		N				Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
329 S MAIN		N				Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				

8813 EAST LOAMI R		N				Maintenance records		C	UNL	NL	N	N/R	N				
8373 LEAD LINE RD		N				2023 Maintenance reecord		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
8621 LEAD LINE RD		N			1990's	Survey response		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
9199 EAST LOAMI RD		N				Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
9127 EAST LOAMI R		N				Maintenance reecord		C	UNL	NL	N	N/R	N				
9235 EAST LOAMI RD		N				Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
9319 EAST LOAMI R		N			Unknown	Survey response		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
9613 EAST LOAMI R		N				Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
9937 EAST LOAMI RD		N				Maintenance reecord		C	UNL	NL	N	N/R	N				
10063 EAST LOAMI RD		N			2019	Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
2 GARNER LN		N				Visual inspection		C	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #01		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #02		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #04		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #05		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #08		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #09		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #10		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #11		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #12		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #13		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #14		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #16		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #17		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #19		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #20		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #21		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #22		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #25		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #26		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #27		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #28		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #29		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #30		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #31		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #32		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #33		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #35		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #37		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #38		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #39		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #42		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #43		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				
723 N MAIN ST #44		N			1970's	Visual inspection		P	Plastic - PVC, HDPE, PEX (P)	NL	N	N/R	N				

[illegible]